



BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
DASARAHALLI		14		Bagalakunte			
Street ID		Street Name		Significant Landmark			
W0393		NA		Bagalagunte			
Segment No.		Total Length (m)					
14/S-W0393/S020550		64.89					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	64.89	77.504255	13.057400	77.504166	13.056820	Bagalagunte Main road	Dead End
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Improvements to CC road & drain at 7th & 15th cross and Other cross road in Bagalagunte Ward No 14		2000000			2017-18		
Year	Type of Work			Other Work Type			
2017 - 2018	Drain Maintenance						
Tender	Work Details			Job No. / Work Code			
Not a Tender				014-18-000037			
Work Order No.	Work Order Date			Period of Extention			
BBMP/E/DD/343/17-18	24/03/2018						
Defect Liability Period From	Defect Liability Period To			Multiple road involved with the same Job No/ Work Code #			
24/03/2018	23/03/2019			No			
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)		Expenditure Booked / Released (Rs)			
KRIDL				1999457.00			
Phone No.		E-Mail ID					
9448512985							

Zone: DASARAHALLI

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0393

Date: 07/05/2018

Time: 14:16:10

RH20180507141610

Page 1 of 1